

# Compare Responses

Event #: 4325

Event Name: Roof Replacement

Number Of Lines: 4

Status: Pending Award

	Coastal Roofing Co Inc	Delta Metals, Inc.	Fabrication Design Concepts	Metalcrafts, Inc.	abc maintenance services, inc	CMS Roofing LLC
<b>Performance Evaluation Score</b>	David Gunnels	Cory Reed	Jennifer Dusterdieck	Donnie Lancaster	harry fender	Curtis DuVall
	(Award All valid only when output is same for all lines)	(Award All valid only when output is same for all lines)	(Award All valid only when output is same for all lines)	(Award All valid only when output is same for all lines)	(Award All valid only when output is same for all lines)	(Award All valid only when output is same for all lines)
<b>Supplier Total Bid Amount</b>	37,714.00	50,925.52	47,428.00	64,811.00	54,542.60	38,068.84
<b>Total Event Score</b>						
<b>Line 1:Open:ROOF REPLACEMENT Output: PO</b>						
<b>Award Quantity 0.0000</b>	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
<b>Line Quantity 1.0000 LO</b>	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
<b>UnitPrice</b>	33,880.00000	48,250.00000	41,800.00000	57,522.00000	49,269.00000	34,821.48000
<b>ExtendedPrice</b>	33,880.00	48,250.00	41,800.00	57,522.00	49,269.00	34,821.48
<b>Total Line Score</b>						
<b>Delivery Date</b>	07/22/2016	07/22/2016	07/22/2016	07/22/2016	07/22/2016	07/22/2016
<b>UOM Detail</b>						
<b>Vendor Item</b>				ROOF REPLACEMENT		
<b>Vendor Item Description</b>				Roof Replacement as specified		

Compare Responses continued...

<b>Line 2:Open:BOARD FOOT TEATED WOOD BLOCKING Output: PO</b>						
<b>Award Quantity 0.0000</b>	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
<b>Line Quantity 60.0000 BF</b>	60.0000	60.0000	60.0000	60.0000	60.0000	60.0000
<b>UnitPrice</b>	2.50000	2.50000	4.00000	2.10000	2.65000	1.00000
<b>ExtendedPrice</b>	150.00	150.00	240.00	126.00	159.00	60.00
<b>Total Line Score</b>						
<b>Delivery Date</b>	07/22/2016	07/22/2016	07/22/2016	07/22/2016	07/22/2016	07/22/2016
<b>UOM Detail</b>						
<b>Vendor Item</b>				BOARD FOOT TREATED WOOD BLOCKING		
<b>Vendor Item Description</b>				Board Foot Treated Wood Blocki		
<b>Line 3:Open:PLYWOOD DECK REPLACEMENT Output: PO</b>						
<b>Award Quantity 0.0000</b>	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
<b>Line Quantity 96.0000 SF</b>	96.0000	96.0000	96.0000	96.0000	96.0000	96.0000
<b>UnitPrice</b>	6.00000	2.87000	4.25000	11.43750	1.35000	1.00000
<b>ExtendedPrice</b>	576.00	275.52	408.00	1,098.00	129.60	96.00
<b>Total Line Score</b>						
<b>Delivery Date</b>	07/22/2016	07/22/2016	07/22/2016	07/22/2016	07/22/2016	07/22/2016
<b>UOM Detail</b>						
<b>Vendor Item</b>				MATCHING PLYWOOD DECK REPLACEMEN		

Compare Responses continued...

Vendor Item Description				Matching Plywood Deck Replacem		
<b>Line 4:Open:ROOF REPLACEMENT FOR DRIVE-THRU Output: No Output</b>						
<b>Award Quantity 0.0000</b>	0.0000	0.0000	0.0000	0.0000	0.0000	0.0000
<b>Line Quantity 1.0000 LO</b>	1.0000	1.0000	1.0000	1.0000	1.0000	1.0000
<b>UnitPrice</b>	3,108.00000	2,250.00000	4,980.00000	6,065.00000	4,985.00000	3,091.36000
<b>ExtendedPrice</b>	3,108.00	2,250.00	4,980.00	6,065.00	4,985.00	3,091.36
<b>Total Line Score</b>						
<b>Delivery Date</b>						
<b>UOM Detail</b>						
<b>Vendor Item</b>				ROOF REPLACEMENT FOR DRIVE-THRU		
<b>Vendor Item Description</b>				Roof Replacement for Drive-Thr		